

Fig. 1






Fig. 2



3/14

Fig. 3



09821816 071601

4/14

Fig. 4 (1)





Fig. 4 (2)



5/14

Fig. 5 (1)






Fig. 5 (2)



09319S-000197

6/14


Fig. 6



009120" 9T8T2860

7/14

Fig. 7



8/14

Fig. 8 (1)




Fig. 8 (2)

<Description of area upper limit values and area lower limit values of measured objects>






Fig. 9



ex) Bad if area difference is 50 or over

10/14


Fig. 10



11/14

Fig. 11

<<Flow of adjacent area determination>>




09821816.071601

Fig. 12

12/14

<<Flow of adjacent area determination process and Examination of each examination range>>



T09120" 9T8T2860

13/14

Fig. 13 (1)





Fig. 13 (2)



09821816-071601

14/14

Fig. 14




Fig. 15

